

**Marion County Courthouse Square  
555 Court Street NE, Salem Oregon  
Remediation Study Final Report  
February 07, 2011**

**Volume Four of Six**




## VOLUME IV

### I. PRESENTATION GRAPHICS

- A. June 09, 2010
- B. July 26, 2010
- C. October 26, 2010
- D. January 20, 2010







Marion County  
Courthouse Square Structural Remediation  
Project Summary  
June 09, 2010

S E R A

## Team Members and Expertise

### Marion County

- Building Owner, Client

### Salem Keizer Transit District

- Building Owner, Client

### SERA Architect

- Project manager and team coordinator
  - Building assessment
- Sustainability Resources
  - Interior Design

### Miller Consulting Engineers

- Structural engineering

### RDH Building Sciences

- Building envelope and waterproofing

- Dave Henderson- Director, Business Services
- Tom Hogstad, Facilities Manager
- Gary Hales, Loss Control Manager
- Steve Frank, Maintenance Supervisor

- Andrew Cooper, Safety and Loss Control Specialist
- Trent McCoy, Facilities Maintenance Supervisor

- Joe Pinzone- Principal-in-charge
- Russ Pitkin- Project Manager
- George Hager- Project Architect, Project coordinator
- Brian Cobb- Project Architect
- Carissa Mylin- Interior Designer
- Russell Holzinger- BIM, graphics, support

- Ray Miller- Structural Engineer
- Eric Watson- Structural Engineer
- Andrew Leichy- Structural Engineer

- Ariel Levy, PE- Building Science Specialist
- Eric Lawrence

## Team Members and Expertise

PAE Consulting Engineers

• Mechanical, Electrical, Plumbing engineering

H&A Construction

• Cost Modeling, Constructability Review

Fortis Construction

• Construction Manager, General Contractor

• Cost Modeling, Constructability Review

GeoDesign

• Geotechnical engineering

David Evans & Associates

• Building Survey

Carlson Testing, Inc.

• Material Testing

- Nick Collins, PE
- Jon Ricket, PE- Mechanical Engineer
- Dennis Bohn, PE- Electrical Engineer

• Bob Able, Cost Estimator

- Pete Smith
- Andy Franklin
- Tom Sowa

- George Saunders, PE, GE
- Scott McDevitt, PE

• Jon Broadwater, PLS

- Mark Powilson, Special Project Department Manager

## Team Members and Expertise

The flow of this presentation. . . .

- Symptoms: The damage we mainly see is caused by some other issue.
  - We observed almost all of the spaces and surfaces to document defects.
- Testing: We investigated key areas to determine the fundamental cause.
  - We opened and revealed specific areas to learn more.
- Diagnosis: Information we've gathered is beginning to be analyzed. They're still more to go.
  - What is the evidence telling us?

## Milestones and Key Events

- Project kickoff meeting March 10, 2010
- Process definition and development March 11 through April 09
  - Onsite observation April 14 through 21
- Geotechnical soil borings April 12 through May 15
  - Full building survey April 15 through May 02
- Exterior brick and window survey May 06 through 08
  - Sidewalk excavation May 01
    - Material testing May 05 through June 11
- Window water infiltration testing May 10 through 29
- Remaining exterior brick and window survey June 26



## SYMPTOMS


### Interior finishes- Walls

- Wall cracking is prevalent throughout the building
  - Progressively more frequent
  - Progressively more numerous



# SYMPTOMS


## Interior finishes- Walls



## SYMPTOMS

### Interior finishes- Ceilings

- Ceiling misalignment is prevalent through the building
  - Misalignment is extremely pervasive with a few buckled ceiling grids
  - Acoustic tiles have sustained damage
  - Nearly all perimeter grids have been damaged





# SYMPTOMS

## Interior finishes- Ceilings



## SYMPTOMS

### Interior finishes- Doors

- Building movement has caused door issues
  - Fire Life Safety doors have been impacted
  - Doors have been modified to fit conditions
  - Many doors are not square within the frame or are warped



# SYMPTOMS

## Interior finishes- Doors






## SYMPTOMS

### Interior finishes- Cabinetry, Casework and Furniture

- Deflection in the floor slabs have caused other damage throughout the building
  - Anchored systems furniture are damaging walls
  - Cabinetry and casework are not level causing function issues
  - Counter top backslashes are detaching from the walls
  - Employee desks are not level



# SYMPTOMS

## Interior finishes- Cabinetry, Casework and Furniture



## SYMPTOMS

### Building equipment

- Areas visually observed include:
  - Main duct risers (east and west shafts)
  - Ductwork, sprinkler piping, electrical equipment above ceiling at worst deflection
  - Basement fan rooms and duct connections
  - Gas pipe riser at the street meter and at the 5<sup>th</sup> Floor
  - Roof top equipment





## SYMPTOMS

### Building equipment


- Equipment damaged related to building movement include:
  - Intake louver at parking garage ramp
  - Fan room wall cracks in the Basement
  - Fan housekeeping pad cracked



## SYMPTOMS

### Building equipment

- A note of special concern
  - Fire/ smoke damper access panels should be installed at west shaft
  - Equipment wear and tear





## SYMPTOMS

### Building Envelope and Waterproofing

- Interior damage from water infiltration includes:
  - Ceiling and soffit staining
  - Window frame staining
  - Water infiltration at the foundation walls



# SYMPTOMS

## Building Envelope and Waterproofing



## SYMPTOMS

### Building Envelope and Waterproofing

- Exterior Observation found:
  - Water infiltration issues at the curtain walls including failed window units
  - Window frames out of alignment
  - Brick control and expansion joints not uniform
  - Window sealant at the end of it's useful life
  - Cracks in the brick facade





# SYMPTOMS

## Building Envelope and Waterproofing



# SYMPTOMS

## Building Envelope and Waterproofing





## Building Envelope and Waterproofing

- Further investigation at the foundation revealed:
  - Installation of the foundation wall damp proofing system
  - Water issues exacerbating an already delicate structural condition
  - Construction defects during installation
  - Missing design detailing and then failed field solutions



# TESTING

## Building Envelope and Waterproofing





# TESTING

## Building Envelope and Waterproofing





# TESTING

## Building Structure


- Exterior brick and window survey and structural observations let to further discoveries:
  - Installed tendons different than design drawings
  - Construction methods have directly contributed to interior damage; slab deflections didn't help



## TESTING

### Building Structure

- Exterior brick and window survey and structural observations led to further discoveries:
  - Quality control issues at the time of construction
  - Observed brick movement revealed deformed structural stud walls



# TESTING

## Building Structure



SE Corner



SW Corner



TESTING

Building Structure



NW Corner



NE Corner

# TESTING

## Geotechnical and Foundations



- Remediation excavations up to 20 feet prior to site development
- Century West reports indicated placement of temporary loose soils but didn't document removal
- Excavations were backfilled and compacted according to specifications.



Photograph 1. Site 6 - Beginning of contaminated soil excavation after overburden removal, facing east.




Photograph 2. Site 6 - Recharging groundwater in excavation, facing southwest.



# TESTING

## Geotechnical and Foundations



- Four soil borings at critical foundation areas where building distress was observed.
- Gravel fill and native soils are generally medium dense to very dense.
- Gravel fill not adequately compacted could lead to isolated settlement areas.



# TESTING

## Geotechnical and Foundations

- Original design recommended bearing pressure of 2500lbs for gravel fill and 6000lbs for native soil.
- An exploratory excavation at observed confluence of building damage.
- Any settlement would have occurred quickly.





## Full Building Survey

- Existing slabs exhibited significant perceptible deflections:
  - Previous survey showed the deflections grew progressively worse
  - Needed a defensible and repeatable methodology
  - Survey portions of the building not previously surveyed





# TESTING

## Full Building Survey



Summary of structure based on as-designed conditions


## Foundation/Soil

- a. Appears all footings designed for 6,000 psf
- b. Per discussions w/GeoDesign, likely to have structural fill present below all footings
- c. Original geotech report notes to use 2,500 psf for footings on fill. However, GeoDesign still would expect only 1-2" of immediate settlement of footings on fill. Would not continue long term
- d. Foundation soil bearing not likely to be contributing factor to condition of structure
- e. May be other issues with punching shear and reinforcing in mat foundations. Final analysis still needs to be performed.

## Analysis of As-designed structure is 95% complete

- High amount of precompression stress
  - Many areas over the industrial standard recommend 300 PSI
  - Some areas around 450 PSI
- High amount of load balancing in east-west spans
  - Up to 200% DL – Typically stay within 80% range
- Calculated deflections at  $\approx$  50% of the field survey deflections

# CONSTRUCTION LOADING: STD DEFLECTION PLAN (INITIAL 30 DAYS)




1.2"

Fourth Floor





SUSTAINED LOAD: STD DEFLECTION PLAN  
D = 0.5L (AFTER 5,000 DAYS)




Fourth Floor

3.5" Field Survey



# FINAL INSTANTANEOUS LOAD: STD DEFLECTION PLAN (D+L)



1.9" (L/240)

Fourth Floor





## Analysis of As-designed structure is 95% complete


- d. A few areas where additional top reinforcement should have been added in original plans for service loading considerations
- e. A few areas where additional reinforcing for strength may be needed
- f. Still need to locate tendon loss calcs from DSI and slab calcs from Century West

## Core Shear Walls

- Preliminary seismic analysis indicates shear walls in north-south direction may be around 50% below seismic demand
- West mat foundation may be under strength in north-south direction also
- Need to locate original structural calculations to review design procedure
- Cracking in core shear walls likely due to restraint forces from P.T. slab


## Material Testing

- Full building survey informed where material samples were to be taken:
  - Gather data from perceived 'good' and 'bad' locations at each floor
  - Each side of slab's pour strip
  - Used a combination of GPR and x-ray to locate cores



## Material Testing

- Concrete core testing results showed less than designed strengths of 5000psi:
  - Ground Floor = 4360psi, 4600psi, 4424psi
  - Second Floor = 3460psi, 4210psi, 3710psi, 4080psi
  - Third Floor = 3960psi, 3490psi, 3800psi, 3500psi
  - Fourth Floor = 4310psi, 3730psi, 4860psi, 4520psi
  - Fifth Floor = 5150psi, 4240psi, 4520psi, 4510psi





## DIAGNOSIS

Nondestructive & destructive testing results

### Petrographic Results

- a. Some variation in thickness
  - i. ACI 117 permits up to 1/4" variation
- b. PH low on top surface likely due to curing compound used
  - i. Not a structural issue
- c. PH is high (12-13) for remainder of slab which is desirable for corrosion protection
- d. % unhydrated cement
  - i. If concrete wasn't cured properly, water could evaporate from the mix which would not allow all particles to be hydrated

DIAGNOSIS  
Core sample results

## Core Sample Results

- 5<sup>th</sup> Floor – Average  $f'_c = 4605$  PSI
- 4<sup>th</sup> Floor – Average  $f'_c = 4355$  PSI
- 3<sup>rd</sup> Floor – Average  $f'_c = 3688$  PSI
- 2<sup>nd</sup> Floor – Average  $f'_c = 3865$  PSI
- 1<sup>st</sup> Floor – Average  $f'_c = 4460$  PSI

Core sample results (continued)

Per ASTM C42, historically, core strengths have been taken as 85% of standard cured molded cylinders

$$5000 \text{ PSI} \times 0.85 = 4,250 \text{ PSI}$$

However, concrete continues to gain strength with age (i.e., 5,000 PSI @ 28 days  $\approx$  5,800 PSI @ 3,650 days. So,  $5,800 \times 0.85 = 4,930 \text{ PSI}$ ).

Average cores should be above 4,930 PSI and none are.

Variation in core length similar to petrographic. Most areas within 1/4" tolerance

**Have not seen GPR results yet; need to review tendon drape**

## North Block Site Observation

- a. Cracked concrete, water penetration in walls and slab, bearing problems
- b. Areas injected have failed – 3 methods used
  - i. Epoxy Injected
  - ii. Cleaned out & Applied Sealant
  - iii. Top Coat
- c. Procedure for destructive testing of slab and inspection of steel strand
- d. Have not been able to locate calculations or testing in records
- e. Analysis has not yet been performed



## Bus Mall Site Observation

- a. Concrete slab shortened 3" in north/south direction
- b. Crack gauges installed
- c. Water penetration through basement walls
- d. Analysis has not yet been performed

# BUS MALL

## Bus Mall Site Observation



## Bus Mall Observation

- Observations include:
  - Cracking of the foundation wall
  - Cracking of non-structural members
  - Cracks at columns with significant damage due to water infiltration





## TYPICAL MOVEMENT OF THE INTERIOR PARTITION

Typical movement of the interior partition walls in the east-west direction throughout the building indicating the settlement of the PT slab. Typically, the movement was measured to be around  $5/8"$ , but some measured greater than  $1"$ .



## FASCIA CONNECTION AND GROUT POCKET



Surface corrosion of the fascia connection as discussed during the meeting. It appears to be an insignificant issue, but does call out the lack of a rust-inhibiting primer coat being applied to the structural connection. In addition, there is a grout pocket to the lower left that appears to be in very good condition with no visual signs of moisture penetration or corrosion of the PT connection.

## THREE GROUT POCKETS ALONG THE NORTH SLAB EDGE

Slab edge along the north building edge and these are part of the banded PT group along Gridline L, which appears to be in very good condition with no visual signs of moisture penetration or corrosion of the PT connection.



## WOOD CHIPS CAST INTO CONCRETE COLUMN



Poor construction methods were used during the construction of the slab; as a full layer of debris was allowed to be cast into the concrete column at Grid D-13 effectively placing a bond breaker approximately 2' below the fifth floor slab. The screw driver was easily driven approximately 2" into the concrete column.



## WOOD CHIPS CAST INTO CONCRETE SLAB

Another indication that poor construction methods were used during the construction of the slab; another pocket of wood debris was cast into the concrete slab approximately at Grid L-10 near the slab edge. The wood debris pocket appears to be approximately 3" in diameter and 1" deep.



## SIGNIFICANT CRACKING IN CONCRETE COLUMN AT GRID A-10



Crack w/spall removed  
at Grid O-10



Cracking that has occurred at each of the concrete columns at the joint between the building and the bus mall (Grids A-10 and O-10). The spall at Grid O-10 was easily removed exposing the reinforcing steel and corrosion on the reinforcing steel due to water penetration.



## GROUT POCKETS ALONG THE BUS MALL SLAB EDGE NEAR GRID F-3



Along the north edge of the bus mall at the expansion joint between the Bus Mall and North Block.

Shows that moisture is flowing through the expansion joint, around the gutter fix and wetting the slab edge, which is causing damage to several of the grout pockets. The grout pocket at the center has spalled and signs of corrosion are visible on the slab edge.



## SIGNIFICANT CRACKING IN CONCRETE COLUMN AT GRID M-1

Cracking has occurred at the concrete column at Grid M-1, as well as moisture penetrating through the basement concrete walls and causing damage to the concrete structure.



## Next Steps . . . . Prognosis

- The Design Team will be analyzing all of the information:
  - Some residual work for the exterior brick and window survey
  - Computer modeling of the testing report results
  - Development and testing of options
  - Cost modeling








# Marion County Courthouse Square Structural Remediation Project Summary June 09, 2010

S E R A



# Mapping of Building Damage


## SYMPTOMS



## Garage Level

# Mapping of Building Damage


## SYMPTOMS



# Ground Floor

# Mapping of Building Damage

## SYMPTOMS




## Second Floor



# Mapping of Building Damage

## SYMPTOMS




### Third Floor



# Mapping of Building Damage

## SYMPTOMS




- WINDOW SILL CRACK
- GYP WALL CRACK
- CM/J CONC WALL CRACK
- ▲ CASEWORK/FURN ISSUE
- DOOR FUNCTION ISSUE
- ⊗ CEILING GRID BUCKLE IN FIELD
- ⊗ CEILING/SOFFIT ISSUE
- CEILING WALL ANGLE BUCKLING
- FLOORS/SLAB CRACK
- WINDOW, CRACK OR DETERIORATION/ DEFORMATION AT EXTERIOR WALL
- WINDOW, BROKEN/DEFECTIVE IGU
- WINDOW, STAINING & EVIDENCE OF WATER AT WINDOW/SILL
- WINDOW, STAINING & EVIDENCE OF WATER AT WALL OR CLG
- WINDOW, INTERIOR GASKET SHORTING COMPLETE

## Fourth Floor

# Mapping of Building Damage

## SYMPTOMS



## Fifth Floor



# Mapping of Building Damage




## Legend

- no with press. diff. Test P / F
- no with press. diff. P = pass
- no with press. diff. F = fail
- sealant failed, compressed, or split
- failed IGU
- short gasket
- open frame joint or frame issue
- crack
- control joint issue

## South Elevation

# SUMMARY

## Mapping of Building Damage




## North Elevation




# SUMMARY

## Mapping of Building Damage




West Elevation



East Elevation

# SUMMARY


## Slab Deflections



## Ground Floor

# SUMMARY

## Slab Deflections




## Second Floor



# SUMMARY

## Slab Deflections



## Third Floor

# SUMMARY

## Slab Deflections



Fourth Floor 

# SUMMARY

## Slab Deflections




# Fifth Floor



# SUMMARY


## Slab Deflections



Ground Floor

# SUMMARY

## Slab Deflections




## Second Floor



# SUMMARY

## Slab Deflections




## Third Floor



# SUMMARY


## Slab Deflections



## Fourth Floor

# SUMMARY

## Slab Deflections




### Fifth Floor



# STRUCTURAL MODEL


## Structural Model





# SLAB SUMMARY

## Slab Summary




## Next Steps . . . . Prognosis

- The Design Team will be analyzing all of the information:
  - Some residual work for the exterior brick and window survey
  - Computer modeling of the testing report results
  - Development and testing of options
  - Cost modeling









# Marion County Courthouse Square Structural Remediation Project Summary

July 26, 2010



# TEAM MEMBERS

1

## MARION COUNTY Building Owner, Client

- Dave Henderson- Director, Business Services
- Tom Hogstad, Facilities Manager
- Gary Hales, Loss Control Manager
- Steve Frank, Maintenance Supervisor
- Andrew Cooper, Safety and Loss Control Specialist
- Trent McCoy, Facilities Maintenance Supervisor

## SALEM KEIZER TRANSIT DISTRICT Building Owner, Client

## SERA ARCHITECT Project manager and team coordinator Building assessment Sustainability Resources Interior Design

- Joe Pinzone- Principal-in-charge
- George Hager- Project Architect
- Gregg Sanders-Senior Project Manager
- Russ Pitkin- Senior Project Manager
- Brian Cobb- Senior Project Architect
- Carissa Mylin- Interior Designer
- Russell Holzinger- BIM, graphics, support

## MILLER CONSULTING ENGINEERS Structural engineering

- Ray Miller- P.E., S.E. Structural Engineer
- Eric Watson- P.E., S.E. Structural Engineer
- Andrew Leichty- P.E. Structural Engineer

## RDH BUILDING SCIENCES Building envelope and waterproofing

- Ariel Levy, PE- Building Science Specialist
- Eric Lawrence



# TEAM MEMBERS

2

**PAE CONSULTING ENGINEERS**  
Mechanical, Electrical, Plumbing Engineering

- Nick Collins, PE- Mechanical Engineer
- Dennis Bohn, PE- Electrical Engineer

**H&A CONSTRUCTION**  
Cost Modeling, Constructability Review

- Bob Able, Cost Estimator

**FORTIS CONSTRUCTION**  
Construction Manager, General Contractor  
Cost Modeling, Constructability Review

- Pete Smith
- Andy Franklin
- Tom Sowa

**GEODESIGN**  
Geotechnical engineering

- George Saunders, PE, GE
- Scott McDevitt, PE

**DAVID EVANS & ASSOCIATES**  
Building Survey

- Jon Broadwater, PLS

**CARLSON TESTING, Inc.**  
Material Testing

- Mark Powlison,  
Special Project Department Manager





# PRESENTATION OUTLINE

3

## WHAT HAVE WE DISCOVERED TO DATE?

- Building Overview
- Basic Concepts
- Observations

## WHAT HAS CHANGED?

- Bus Mall Structure
  - Action Plan and immediate Action
- Building Structure
  - Action Plan and Immediate Action
- Bus Mall Pavers

## WHAT ARE THE NEXT STEPS?

- Impact to Agencies
- Current Work
- Next Steps



# HOW INFORMATION IS PRESENTED

4

The flow of this presentation. . . .

**Concepts:** The underlying principles of basic structural systems used and deficiencies observed

**Observations:** The damage we mainly see is caused by some other issue.  
We observed almost all of the spaces and surfaces to document defects.

**Testing:** We investigated key areas to determine the fundamental cause.  
We opened and revealed specific areas to learn more.

**Summary:** Results, recommendations, and next steps.



# MILESTONES & KEY EVENTS

5

Project kickoff meeting	March 10, 2010
Process definition and development	March 11 through April 09
On-site observation	April 14 through 21
Geotechnical soil borings	April 12 through May 15
Full building survey	April 15 through May 02
Exterior brick and window survey	May 06 through 08
Sidewalk excavation	May 01, 2010
Material testing	May 05 through June 11
Window water infiltration testing	May 10 through 29





# MILESTONES & KEY EVENTS

6

Project Summary Presentation	June 09, 2010
Analysis of Bus Mall Structure	June 14 through June 28
Remaining exterior brick and window survey	June 26, 2010
On-site observation of Bus Mall	June 30, 2010
Closure and Relocation of Bus Mall	July 02, 2010
Analysis of Building structural system	July 01 through July 16
Implementation of 90-Day Relocation Plan	July 19, 2010
On-site observation of Building columns	July 24, 2010
Remediation Options for entire site	Mid-August through Mid-September 2010
All Building occupants relocated	End of October 2010



# WHAT HAVE WE DISCOVERED TO DATE?


7

- Building overview
- Basic Concepts
- Observations



# COURTHOUSE SQUARE

8




- Observe Problems
- Test for Specific Concerns
- Develop Remediation Options



# BUILDING OVERVIEW

9




Garage Levels



# BUILDING OVERVIEW

10




Ground Floor



# BUILDING OVERVIEW

11



- WINDOW SILL CRACK
- GYP WALL CRACK
- CMU/CONC WALL CRACK
- ▼ CASEWORK/FURN ISSUE
- DOOR FUNCTION ISSUE
- ⊗ CEILING GRID BUCKLE IN FIELD
- ⊗ CEILING/OFFIT ISSUE
- WINDOW STAINING & EVIDENCE OF WATER AT WINDOW/SILL
- FLOORS/LAB CRACK
- WINDOW; STAINING & EVIDENCE OF WATER AT WALL OR CLS
- WINDOW; INTERIOR GASKET SHORT/INCOMPLETE
- CEILING WALL ANGLE BUCKLING
- WINDOW; CRACK OR DETERIORATION/ DEFORMATION AT EXTERIOR WALL
- WINDOW; BROKEN/DEFECTIVE IGU
- WINDOW; STAINING & EVIDENCE OF WATER AT WINDOW/SILL
- WINDOW; STAINING & EVIDENCE OF WATER AT WALL OR CLS
- WINDOW; INTERIOR GASKET SHORT/INCOMPLETE


Second Floor





# BUILDING OVERVIEW

12



- WINDOW SILL CRACK
- GYP WALL CRACK
- CMU/CONC WALL CRACK
- WINDOW; STAINING & EVIDENCE OF WATER AT WINDOW/SILL
- WINDOW; STAINING & EVIDENCE OF WATER AT WALL OR CLG
- WINDOW; INTERIOR GASKET SHORTING/COMPLETE
- DOOR FUNCTION ISSUE
- CEILING GRID BUCKLE IN FIELD
- ⊗ CEILING/SOFFIT ISSUE
- CEILING WALL ANGLE BUCKLING
- FLOOR/SLAB CRACK
- WINDOW; CRACK OR DETERIORATION/ DEFORMATION AT EXTERIOR WALL
- WINDOW; BROKEN/DEFECTIVE IGU

Third Floor




**Cherriots**  
SALEM-KEIZER TRANSIT



# BUILDING OVERVIEW

13



Fourth Floor




**Cherriobts**  
SALEM-KEIZER TRANSIT





# BUILDING OVERVIEW

14



Fifth Floor



**Cherriobts**  
SALEM-KEIZER TRANSIT

MARION COUNTY COURTHOUSE SQUARE & BUS MALL REMEDIATION PROJECT JULY 26, 2010





# BUILDING OVERVIEW

15



### Legend

- no with  
press. press. diff. diff.
- sealant failed, compressed, or split
- failed IGU
- crack
- short gasket
- open frame joint or frame issue
- control joint issue
- Test P / F
- P = pass
- F = fail

South Elevation



# BUILDING OVERVIEW

16



### Legend

- sealant failed, compressed, or split
- short gasket
- open frame joint or frame issue
- failed IGU
- crack
- control joint issue

North Elevation




**Cherriobts**  
SALEM-KEIZER TRANSIT




# BUILDING OVERVIEW

17



West Elevation



East Elevation



**Cherriots**  
SALEM-KEIZER TRANSIT





# BASIC CONCEPTS

18


- Fundamentals of concrete slabs
- Fundamentals of seismic design
- Fundamentals of column design



# BASIC CONCEPTS



19

## DEFLECTIONS/STRENGTHS



# HOW POST TENSIONED CONCRETE WORKS


CONSTRUCTION TYPE (POST-TENSIONING)






# HOW POST TENSIONED CONCRETE WORKS

21



# WHAT HAPPENS WHEN IT FAILS

22



# OBSERVED SLAB DEFLECTION

23




Ground Floor







# OBSERVED SLAB DEFLECTION 25



Third Floor



MARION COUNTY COURTHOUSE SQUARE & BUS MALL REMEDIATION PROJECT JULY 26, 2010



OREGON



# OBSERVED SLAB DEFLECTION

26



Fourth Floor




**Cherriots**  
SALEM-KEIZER TRANSIT





# OBSERVED SLAB DEFLECTION 27



Fifth Floor




MARION COUNTY COURTHOUSE SQUARE & BUS MALL REMEDIATION PROJECT JULY 26, 2010




# OBSERVED SLAB DEFLECTION

28



# WALLS


29





# CEILINGS

30



# DOORS

31



# CASEWORK


32






# SHRINKAGE/SHORTENING

33



# SHORTENING PER FLOOR

34



# BUILDING STRUCTURE

35



SE Corner




SW Corner



# BUILDING STRUCTURE

36



# BUILDING ENVELOPE & WATERPROOFING

37

Exterior Observation found:


- Water infiltration issues at the curtain walls including failed window units
- Window frames out of alignment
- Brick control and expansion joints not uniform
- Window sealant at the end of it's useful life





# BUILDING ENVELOPE & WATERPROOFING


38






# SEISMIC RESISTANCE

39




# LATERAL RESISTIVE ELEMENTS 40



# First Floor Shear Wall Deficiencies

41




Shear Strength Deficiency




# Second Floor Shear Wall Deficiencies

42



# Third Floor Shear Wall Deficiencies


43



Shear Strength Deficiency

# Fourth Floor Shear Wall Deficiencies


44






# Fifth Floor Shear Wall Deficiencies

45




Shear Strength Deficiency

# Roof Shear Wall Deficiencies



# NORTH BLOCK


47





# NORTH BLOCK

48




MARION COUNTY COURTHOUSE SQUARE & BUS MALL REMEDIATION PROJECT JULY 26, 2010

SERA

# NORTH BLOCK

49



# NORTH BLOCK

50

## North Block Site Observation

- a. Cracked concrete, water penetration in walls and slab, bearing problems
- b. Areas injected have failed – 3 methods used
  - i. Epoxy Injected
  - ii. Cleaned out & Applied Sealant
  - iii. Top Coat
- c. Procedure for destructive testing of slab and inspection of steel tendons ongoing
- d. Records and data are poor and incomplete.



# NORTH BLOCK

51





# NORTH BLOCK

52




# MATERIAL TESTING

53

Full building survey informed where material samples were to be taken:

- Gather data from perceived 'good' and 'bad' locations at each floor
- Each side of slab's pour strip
- Used a combination of GPR and x-ray to locate cores






# MATERIAL TESTING: Compressive Tests 54

Concrete testing results showed less than designed strengths of 5000psi:  
Actual strengths are:

- Ground Floor = 4360psi, 4600psi, 4424psi
- Second Floor = 3460psi, 4210psi, 3710psi, 4080psi
- Third Floor = 3960psi, 3490psi, 3800psi, 3500psi
- Fourth Floor = 4310psi, 3730psi, 4860psi, 4520psi
- Fifth Floor = 5150psi, 4240psi, 4520psi, 4510psi

Computer modeling protocol stipulates using the ACI 214 Design Manual.



# MATERIAL TESTING: PETROGRAPHIC RESULTS

55

## **Some variation in slab thickness**

- ACI 117 permits up to 1/4" variation

## **pH low on top surface likely due to curing compound used**

- Not a structural issue

## **pH is high for remainder of slab which is desirable for corrosion protection**


## **Percent of unhydrated cement**

- If concrete wasn't cured properly, water could evaporate from the mix which would not allow all particles to be hydrated (chemical curing process)




# PUNCHING SHEAR

56



# PUNCHING SHEAR

57



# PUNCHING SHEAR

58



Radial cracks

Radiating cracks

Image Source: University of Michigan-

<http://www-personal.umich.edu/~gjp/m/NEES%20Project%20Website/Slab.htm>

# PUNCHING SHEAR


59






# PUNCHING SHEAR

60



# Building Footing Deficiencies

61




 Punching Shear Stress More Than 1/3 Greater Than Code Allowance


 Punching Shear Stress More Than 10% Greater Than Code Allowance

# First Floor: Punching Shear Stress Plan

62




- █ Exceeds Code Stress Limits w/5,000 psi Concrete and Actual Core Strengths
- █ Exceeds Stress Limits using Actual Code Strengths
- █ Stress More than 1/3 Greater than Code Allowable Based on Actual Core Strengths
- █ Stress more than 1/3 Greater than Code Allowance Based on Original Design Strength (5,000 psi) and Actual Core Strengths



# Second Floor: Punching Shear

63

## Stress Plan




- Exceeds Code Stress Limits w/5,000 psi Concrete Design Strength
- Exceeds Stress Limits using Actual Code Strengths
- Stress More than 1/3 Greater than Code Allowable Based on Actual Core Strengths ("Dangerous" Condition)
- Stress more than 1/3 Greater than Code Allowance Based on Original Design Strength (5,000 psi) and Actual Core Strengths ("Dangerous" Condition)





# Third Floor: Punching Shear Stress Plan

64




- Exceeds Code Stress Limits w/5,000 psi Concrete Design Strength
- Exceeds Stress Limits using Actual Code Strengths
- Stress More than 1/3 Greater than Code Allowable Based on Actual Core Strengths ("Dangerous" Condition)
- Stress more than 1/3 Greater than Code Allowance Based on Original Design Strength (5,000 psi) and Actual Core Strengths ("Dangerous" Condition)



# Fourth Floor: Punching Shear Stress Plan


65



- Exceeds Code Stress Limits w/5,000 psi Concrete Design Strength
- Exceeds Stress Limits using Actual Code Strengths
- Stress More than 1/3 Greater than Code Allowable Based on Actual Core Strengths ("Dangerous" Condition)
- Stress more than 1/3 Greater than Code Allowance Based on Original Design Strength (5,000 psi) and Actual Core Strengths ("Dangerous" Condition)



# Fifth Floor: Punching Shear Stress Plan




- Exceeds Code Stress Limits w/5,000 psi Concrete Design Strength
- Exceeds Stress Limits using Actual Code Strengths
- Stress More than 1/3 Greater than Code Allowable Based on Actual Core Strengths ("Dangerous" Condition)
- Stress more than 1/3 Greater than Code Allowance Based on Original Design Strength (5,000 psi) and Actual Core Strengths ("Dangerous" Condition)



# Roof: Punching Shear Stress Plan

67




- Exceeds Code Stress Limits w/5,000 psi Concrete Design Strength
- Exceeds Stress Limits using Actual Code Strengths
- Stress More than 1/3 Greater than Code Allowable Based on Actual Core Strengths ("Dangerous" Condition)

Stress more than 1/3 Greater than Code Allowance Based on Original Design Strength (5,000 psi) and Actual Core Strengths ("Dangerous" Condition)






# COLUMN DESIGN



Column Design

# Roof Columns




All Columns within 10% of Design Capacity

-  More than 10% Beyond Code Limit
-  More than 33% Beyond Code Limit



# Fifth Floor Columns

70



More than 10% Beyond Code Limit

More than 33% Beyond Code Limit



# Fourth Floor Columns

71




- More than 10% Beyond Code Limit
- More than 33% Beyond Code Limit





# Third Floor Columns

72




More than 10% Beyond Code Limit

More than 33% Beyond Code Limit



# Second Floor Columns

73




More than 10% Beyond Code Limit

More than 33% Beyond Code Limit



# First Floor Columns

74



■ More than 10% Beyond Code Limit

■ More than 33% Beyond Code Limit



# OTHER OBSERVATIONS

75

- Design Issues
- Construction Issues
- Material Quality Issues
- Building Equipment
- Geotechnical Survey





# DESIGN ISSUES: Detailing

76



# DESIGN ISSUES: Detailing

77






# DESIGN ISSUES: Detailing

78




# DESIGN ISSUES: Structural Design <sup>79</sup>






# DESIGN ISSUES: Structural Design <sup>80</sup>




# Typical Slab Top Reinforcing Steel Deficiencies at First Floor

81




# Typical Slab Bottom Reinforcing Steel Deficiencies at First Floor

82



# Typical Slab Top Reinforcing Steel 83

## Deficiencies at 2nd-5th Floors + Roof




### Keynotes

1. Insufficient Top Reinforcing under Service Loads
2. Insufficient Top Reinforcing for Flexural Strength
3. Insufficient Top Reinforcing for Service and Strength
4. Column strip top Stress Exceeded
5. Insufficient Top Reinforcing Steel at 3<sup>rd</sup>, 4<sup>th</sup> Floors



# Typical Slab Bottom Reinforcing Steel Deficiencies at Floors 2 - Roof

84



# DESIGN ISSUES: Structural Design 85

File: g:\share\portland\structur\open\40903\00104\adapt\2druns\crthbdcl.res

12/29/1998 @ 02:39:56pm Page: 9

- 4 = EDGE COLUMN (PARALLEL TO SPAN)
- 5 = BEAM OR WALL (PUNCHING SHEAR CHECK NOT APPLICABLE)
- 6 = STRIP TOO NARROW TO DEVELOP PUNCHING SHEAR
- 1 = STRESS WITHIN SECTION #1 GOVERNS (COL.CAP OR SLAB)
- 2 = STRESS WITHIN SECTION #2 GOVERNS (DROP PANEL OR SLAB)

JNT	COND.	shear k	moment k-ft	due to shear	due to moment	TOTAL	allowable	STRESS RATIO	CASE
-1-	-2-	-3-	-4-	-5-	-6-	-7-	-8-	-9-	-10-
1	5								
2	1	612.91	80.06	785.21	63.88	849.09	316.62	2.68	1
3	1	588.31	66.73	753.71	53.25	806.95	316.62	2.55	1
4	1	515.48	74.86	660.40	59.74	720.13	291.12	2.47	1
5	1	189.53	8.06	242.81	6.43	249.24	291.12	.86	1
6	1	501.09	79.19	641.96	63.19	705.15	291.12	2.42	1
7	1	590.86	53.52	756.97	42.71	799.67	291.12	2.75	1
8	5								

STRESS RATIOS EXCEED ALLOWABLE VALUES, REVISE SECTION GEOMETRY.



# CONSTRUCTION ISSUES

86

Wood Chips Cast Into Concrete Column



Poor construction methods were used during the construction of the slab; as a full layer of debris was allowed to be cast into the concrete column at Fourth Floor Grid D-13 effectively placing a bond breaker approximately 2' below the fifth floor slab. The screw driver was easily driven approximately 2" into the concrete column.



# CONSTRUCTION ISSUES

87






# CONSTRUCTION ISSUES



Reinforcing bar exposed at the bottom of the Bus Mall slab.



# CONSTRUCTION ISSUES

89



Debris on the form work cast into the Bus Mall slab.







# MATERIAL QUALITY ISSUES

90

Standing water in window



# MATERIAL QUALITY ISSUES:

## Concrete Design

91

- Concrete Strength- Designed for 5000psi; tested on average of 4151psi.
- Fiber reinforcement was designed in but not found in the concrete. Fiber is used for ductility and to reduce cracking from shrinkage.
- All concrete mixes required air entrainment. This created more than normal voids.



# BUILDING EQUIPMENT

92

Areas visually observed include:

- Main duct risers (east and west shafts)
- Ductwork, sprinkler piping, electrical equipment above ceiling at worst deflection
- Basement fan rooms and duct connections
- Gas pipe riser at the street



# BUILDING EQUIPMENT

93

Equipment damaged related to building movement include:

- Intake louver at parking garage ramp
- Fan room wall cracks in the Basement
- Fan housekeeping pad cracked



# BUILDING EQUIPMENT

94

A note of special concern

- Fire/ smoke damper access panels should be installed at west shaft
- Equipment wear and tear



# GEOTECHNICAL SURVEY

95



- Remediation excavations up to 20 feet prior to site development
- Century West reports indicated placement of temporary loose soils but didn't document removal
- Excavations were backfilled and compacted according to specifications.





# GEOTECHNICAL SURVEY

96



# GEOTECHNICAL SURVEY

97

Summary of structure based on as-designed conditions

## Foundation/Soil

- a. Appears all footings designed for 6,000 psf
- b. Per discussions w/GeoDesign, likely to have structural fill present below all footings
- c. Original geotech report notes to use 2,500 psf for footings on fill. However, GeoDesign still would expect only 1-2" of immediate settlement of footings on fill. Would not continue long term
- d. Foundation soil bearing not likely to be contributing factor to condition of structural problems



# WHAT HAS CHANGED?


98

- Bus Mall Structure
  - Action Plan and immediate Action
- Building Structure
  - Action Plan and Immediate Action
- Bus Mall Pavers



# BUS MALL STRUCTURE


99





# BUS MALL STRUCTURE

100




MARION COUNTY COURTHOUSE SQUARE & BUS MALL REMEDIATION PROJECT JULY 26, 2010

SERA

# BUS MALL STRUCTURE

101



MARION COUNTY COURTHOUSE SQUARE & BUS MALL REMEDIATION PROJECT JULY 26, 2010



# BUS MALL SITE OBSERVATION

102





# BUS MALL SITE OBSERVATION

103

Observations include:

- Cracking of the foundation wall
- Cracking of non-structural members
- Cracks at columns with significant damage due to water infiltration





# BUS MALL WATER INTRUSION

104

## Significant Cracking in Concrete Column at Grid M-10a



Cracking has occurred at the concrete column at Grid M-10a, as well as moisture penetrating through the basement concrete walls and causing damage to the concrete structure.

# PUNCHING SHEAR

105





# PUNCHING SHEAR

106



# Bus Mall Footings


107






# Typical Slab Top Reinforcing Steel At Bus Mall

108




# Typical Slab Bottom Reinforcing Steel At Bus Mall

109



# Bus Mall Punching Shear Stress


110



Stress more than 1/3 Greater Than Code Allowance

# Bus Mall Punching Shear Stress

111



Column Exceeds Code Limits  
Under Dead Load Only






# BUS MALL PAVERS

112

CHEMEKETA STREET



CHURCH STREET

HIGH STREET

COURT STREET



# PAVERS

113





# PAVERS

114



# WHAT ARE THE NEXT STEPS?

115

- Impact to Agencies
- Current Work
- Next Steps





# IMPACT TO AGENCIES

116

**Summary:** Investigation is ongoing. Information and analysis is evolving.

**Bus Mall:** Determined to be “**imminently dangerous**”. Based on analysis of the week of June 19, 2010. Bus Mall and parking garage closed and temporarily relocated.

**Building:** Determined to be “**dangerous**”. Based on analysis of the week of July 19, 2010. Decision to relocate operations and employees within 90 days.




# CURRENT WORK

117


- Building occupants relocated within 90 days.
- Testing for evidence of failure mechanisms.
- Testing for Tendon Strength & Tension
- Testing for Shear Wall & Column Concrete Strength
- Ongoing monitoring for potential Tendon ruptures.



# BUILDING NEXT STEPS



# BUS MALL NEXT STEPS






# MILESTONES & KEY EVENTS

120

Implementation of 90-Day Relocation Plan	July 19, 2010
On-site observation of Building columns	July 24, 2010
Remediation Options for entire site	Mid-August through Mid-November 2010
All Building occupants relocated	End of October 2010





# QUESTIONS?



MARION COUNTY COURTHOUSE SQUARE & BUS MALL REMEDIATION PROJECT JULY 26, 2010







# Marion County Courthouse Square Structural Remediation Project Summary

October 26, 2010



# TEAM MEMBERS

**MARION COUNTY**  
*Building Owner, Client*

**SALEM KEIZER TRANSIT DISTRICT**  
*Building Owner, Client*

**SERA ARCHITECTS**  
*Project manager and team coordinator*  
*Building assessment*  
*Sustainability Resources*  
*Interior Design*

**FORTIS CONSTRUCTION**  
*Construction Manager, General Contractor*  
*Cost Modeling, Constructability Review*

**PAE CONSULTING ENGINEERS**  
*Mechanical, Electrical, Plumbing engineering*

**MILLER CONSULTING ENGINEERS**  
*Structural engineering*

**H&A CONSTRUCTION**  
*Cost Modeling, Constructability Review*

**RDH BUILDING SCIENCES**  
*Building envelope and waterproofing*

**GEODESIGN**  
*Geotechnical engineering*

**PSI**  
*Material Testing*

**DAVID EVANS & ASSOCIATES**  
*Building Survey*

**CARLSON TESTING, Inc.**  
*Material Testing*





# PROGRESS REPORT - PAST

To get to our July 26, 2010 Presentation the team:

- Conducted thorough, methodical and efficient investigations broken out by team member.
- Determined that the building and transit mall had enough significant structural deficiencies which required an efficient relocation of building personnel.
  - Punching Shear
  - Concrete Strength
  - Inadequate gravity load capacity
- Through geotechnical analysis; determined that there were no settlement issues associated with sub-grade deficiencies or foundations.
- The geotechnical firm did not find any evidence of an underground river or creek.
- The buoyancy plugs appear to be installed and working as intended.
- The differential settling between the building and the sidewalk is a result of the sidewalk being built over an inadequately compacted fill.



# PROGRESS REPORT - PRESENT

Following our July 26, 2010 Presentation the team:

- Determined we may need a materials scientist to augment the investigation.
- Generated a number of building remediation scenarios and are proposing a few of those for further development (see executive summary for other options)


BUILDING	BUS MALL	NORTH BLOCK	OVERALL
Demolish existing building to bare land	Demolish to bare land	Demolish to bare land	Demolish to bare land
Minimum remediation for occupancy	Open top / parking below	Eliminate hazard	Convert entire building to parking + add new transit and MC office and other partners on current property
Replace / Repair for 100% intended use	Transition top / no parking below		
	Replace / Repair for 100% intended use		

- Working to provide a cost estimate for the full demolition of the building.
- Brought on another 3<sup>rd</sup> party materials testing firm (PSI) to do an independent analysis.


Here are the current test results from PSI and their comparison to Carlson Testing, Inc.:



# Testing Locations - Second Floor




# Testing Locations - Third Floor






# Testing Locations - Fourth Floor



# Testing Locations - Fifth Floor



# Concrete Compressive Core Strength Test Comparison

	Carlson	PSI
Testing Locations	lbs/in <sup>2</sup> (psi)	lbs/in <sup>2</sup> (psi)
5A-2	5150	4360
5A-3		4240
5C-1	4520	3690
5C-2		3680
4B-1	3730	3480
4B-2		3810
4C-1	4860	4020
4C-2		4600
3B-1	3490	3330
3B-2		3480
3C-1	3800	3600
3C-2		3620
2A-2	3460	3040
2A-3		3770
2C-1	3710	3270
2C-2		3360



# Petrographic Test Comparison

Carlson	PSI
<p style="text-align: center;">4 - 6% VOIDS</p>	<p style="text-align: center;">1.25 - 1.4% VOIDS</p>
<p>Indicating <b>high</b> void content concrete</p> <p style="text-align: center;"><b>3%</b> voids is the average standard for concrete</p>	<p>Indicating abnormally <b>low</b> void content concrete</p>






# Water:Cement Ratio Test Comparison

Carlson	PSI
<p style="text-align: center;"><b>NORMAL</b> WATER TO CEMENT RATIO</p>	<p style="text-align: center;"><b>HIGH</b> WATER TO CEMENT RATIO</p>
<p>Indicating a Stiffer/ <b>Stronger</b> Mix</p>	<p>Indicating a More Workable/ <b>Weaker</b> Mix</p>




# Micro-fractures in the Concrete




Carlson	PSI
<b>MINIMAL</b>	<b>EXCESSIVE</b>
<p>Excessive Micro-fractures would tend to indicate overstressed concrete and a potential for leading to in place concrete strength degradation.</p> <p><b>(It gets weaker.)</b></p>	



PHOTOGRAPHS



Photograph #1 - Sample 06033-1. Change in paste color can be seen at top surface and lower right corner.



Photograph #2 - Sample 06033-2. Color change can be seen in paste at top surface as well as the bulk paste.




# PROGRESS REPORT - FUTURE

## The Next Steps:

- Work with the respective Boards to determine which options they want the project team to pursue.
- Develop those options to a sufficient level for rough cost estimating and decision making purposes.
- Perform the tendon strength and tension test for use in analyzing the options chosen.
- Present those options and costs to the respective Boards.
- The Boards will then need to provide the project team direction.







# QUESTIONS?



*Cherriots*  
SALEM-KEIZER TRANSIT

MARION COUNTY COURTHOUSE SQUARE & BUS MALL REMEDIATION PROJECT    October 26, 2010









# Marion County Courthouse Square Structural Remediation Project Summary

January 20, 2011



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011



MILLER  
CONSULTING  
ENGINEERS, INC.



# TEAM MEMBERS

**MARION COUNTY**  
*Building Owner, Client*

**SALEM KEIZER TRANSIT DISTRICT**  
*Building Owner, Client*

**SERA ARCHITECTS**  
*Project manager and team coordinator*  
*Building assessment*  
*Sustainability Resources*  
*Interior Design*

**FORTIS CONSTRUCTION**  
*Construction Manager, General Contractor*  
*Cost Modeling, Constructability Review*  
**PAE CONSULTING ENGINEERS**  
*Mechanical, Electrical, Plumbing engineering*

**MILLER CONSULTING ENGINEERS**  
*Structural engineering*

**H&A CONSTRUCTION**  
*Cost Modeling, Constructability Review*

**RDH BUILDING SCIENCES**  
*Building envelope and waterproofing*

**GEODESIGN**  
*Geotechnical engineering*

**PSI**  
*Material Testing*

**CARLSON TESTING, Inc.**  
*Material Testing*


**CTL GROUP**  
*Material Testing*

**DAVID EVANS & ASSOCIATES**  
*Building Survey*





# SITE ORIENTATION: ANALYZED IN THREE PARTS



# SUMMARY OF KEY ACTIVITIES

- Conducted **thorough, methodical, and efficient investigations** broken out by team member.
- Determined that **the building and transit mall** had enough **significant structural deficiencies** which required an efficient relocation of building personnel.
  - **Punching Shear**
  - **Concrete Strength**
  - **Inadequate gravity load capacity at columns and foundations**
- Through geotechnical analysis; determined that there were **no settlement issues** associated with **sub-grade deficiencies** or foundations.
- The **differential settling** between the building and the sidewalk is a result of the **sidewalk being built over inadequately compacted fill.**
- Brought on two 3<sup>rd</sup> party materials testing firm (PSI and CTL Group) to do independent analyses.

# MILESTONES & KEY EVENTS

Project kickoff meeting	March 10, 2010
On-site investigations	April through May
Initial material testing	May through July
Building surveys	April 2010, September, January 2011
Bus mall closure	July 2, 2010
Building closure and Relocation	August through September
Second material testing	September and October
Third material testing	December 2010
Final report and presentation	January 2011



# HOW INFORMATION IS PRESENTED


- Design
  - Floors : Columns : Seismic system
- Materials
  - Compressive Tests : Void Analysis : Water to Cement Ratio : Microfractures
- Construction Issues
- Results of Design, Materials, and Construction Issues
- Impacts
- Remediation Options
- Appendices






# FLOOR DESIGN BASIC CONCEPTS: HOW POST TENSIONED (PT) CONCRETE WORKS

CONSTRUCTION TYPE (POST-TENSIONING)




- PLACE FORMS
- PLACE TENDONS
- POUR CONCRETE




- CONCRETE ACHIEVES MINIMUM STRENGTH
- TENSION CONCRETE
- REMOVE FORMS

# FLOOR DESIGN BASIC CONCEPTS: PT SLAB DIAGRAM




# FLOOR DESIGN ACTUAL CONDITIONS: SHRINKAGE AND SHORTENING

- Shortening due to high pre-compressive stress and dead load balancing
- Shrinkage due to material challenges



# FLOOR DESIGN ACTUAL CONDITIONS: SECTION DIAGRAM

- Observed column crack patterns are consistent in building and bus mall





# FLOOR DESIGN ACTUAL CONDITIONS:

## BUS MALL SHRINKAGE AND SHORTENING



# FLOOR DESIGN ACTUAL CONDITIONS: NORTH BLOCK SHRINKAGE AND SHORTENING




APRIL 2010



DECEMBER 2010


# COLUMN DESIGN BASIC CONCEPTS



WHAT WAS  
DESIGNED AND  
INSTALLED


TYPICAL  
COLUMN  
THICKNESS

# COLUMN DESIGN BASIC CONCEPTS






# COLUMN DESIGN BASIC CONCEPTS



## INSUFFICIENT CAPACITY



## SUFFICIENT CAPACITY

- Appropriate slab thickness and transition reinforcing
- Column capitals can supplement

# COLUMN DESIGN ACTUAL CALCULATIONS:

## Punching Shear


File: g:\share\portland\structur\open\40903\00104\adapt\2druns\crthbdcl.res

12/29/1998 @ 02:39:56pm Page: 9

- 4 = EDGE COLUMN (PARALLEL TO SPAN)
- 5 = BEAM OR WALL (PUNCHING SHEAR CHECK NOT APPLICABLE)
- 6 = STRIP TOO NARROW TO DEVELOP PUNCHING SHEAR
- 1 = STRESS WITHIN SECTION #1 GOVERNS (COL.CAP OR SLAB)
- 2 = STRESS WITHIN SECTION #2 GOVERNS (DROP PANEL OR SLAB)

24"

JMT	COND.	shear k	moment k-ft	due to shear	due to moment	TOTAL	allowable	STRESS RATIO	CASE
1	2	3	4	5	6	7	8	9	10
1	5	612.91	80.06	785.21	63.88	849.09	316.62	2.68	1
3	1	588.31	66.73	753.71	53.25	806.95	316.62	2.55	1
4	1	515.48	74.86	660.40	59.74	720.13	291.12	2.47	1
5	1	189.53	6.06	242.81	6.43	249.24	291.12	.86	1
6	1	501.09	79.19	641.96	63.19	705.15	291.12	2.42	1
7	1	590.86	53.52	756.97	42.71	799.67	291.12	2.75	1
8	5								



ACTUAL COURTHOUSE SQUARE INSTALLATION


STRESS RATIOS EXCEED ALLOWABLE VALUES, REVISE SECTION GEOMETRY.




MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011



# COLUMN DESIGN ACTUAL CONDITIONS: PERCENTAGE OF COLUMN FAILURE



# COLUMN DESIGN: LABORATORY TEST EXAMPLE





RADIAL CRACKS

RADIATING CRACKS

Image Source: University of Michigan-  
<http://www-personal.umich.edu/~gjpm/NEES%20Project%20Website/Slab.htm>





# COLUMN DESIGN ACTUAL CONDITIONS: BUILDING PUNCHING SHEAR



PUNCHING SHEAR CRACKS



# COLUMN DESIGN ACTUAL CONDITIONS: BUILDING PUNCHING SHEAR



PUNCHING SHEAR CRACKS





# COLUMN DESIGN ACTUAL CONDITIONS: BUS MALL PUNCHING SHEAR






# COLUMN DESIGN ACTUAL CONDITIONS: BUS MALL PUNCHING SHEAR






# SEISMIC DESIGN BASIC CONCEPT




TYPICAL SEISMIC FORCES



FORCES WANT TO ROTATE BUILDINGS

# SEISMIC DESIGN BASIC CONCEPT:


## LOAD DIAGRAM AND BOUNDARY ELEMENTS



LOAD INCREASES  
TOWARDS BOTTOM




# SEISMIC DESIGN ACTUAL CONDITION: LOAD DIAGRAM AND BOUNDARY ELEMENTS



LOAD INCREASES  
TOWARDS BOTTOM



# SEISMIC DESIGN BASIC CONCEPT: LATERAL RESISTIVE ELEMENTS





# MATERIALS: CONCRETE COMPRESSIVE CORE STRENGTH TEST COMPARISON

Testing Locations		Carlson MAY 2010 Lbs/in <sup>2</sup> (psi)	PSI SEPT 2010 Lbs/in <sup>2</sup> (psi)
Fifth Floor	5A-2	5150	4360
	5A-3		4240
	5C-1	4520	3690
	5C-2		3680
Fourth Floor	4B-1	3730	3480
	4B-2		3810
	4C-1	4860	4020
	4C-2		4600
Third Floor	3B-1	3490	3330
	3B-2		3480
	3C-1	3800	3600
	3C-2		3620
Second Floor	2A-2	3460	3040
	2A-3		3770
	2C-1	3710	3270
	2C-2		3360

PSI results  
corroborate  
Carlson results



# MATERIALS: 2010 VOID ANALYSIS COMPARISON

Carlson 11 TESTS	PSI 2 TESTS	CTL Group 8 TESTS
4 - 6% VOIDS	1.25 - 1.4% VOIDS	1 - 5% VOIDS
Indicating <b>high</b> void content concrete	Indicating <b>low</b> void content concrete	Indicating <b>low to high</b> void content concrete
3% voids is the average standard for concrete		

CTL Group results corroborate PSI results

Void content directly relates to concrete strength



# MATERIALS: 2010 WATER : CEMENT RATIO TEST COMPARISON

Carlson	PSI	CTL Group
<p><b>NORMAL</b> WATER TO CEMENT RATIO</p>	<p><b>HIGH</b> WATER TO CEMENT RATIO</p>	<p><b>HIGH</b> WATER TO CEMENT RATIO</p>
<p>Indicating a Stiffer / <b>Stronger</b> Mix</p>	<p>Indicating a More Workable / <b>Weaker</b> Mix</p>	<p>Indicating a More Workable / <b>Weaker</b> Mix</p>

CTL Group results  
corroborate  
PSI results



# MATERIALS: WATER : CEMENT RATIO


<p>1999 CONSTRUCTION SUBMITTAL</p> <p>Mix Design</p> <p>Cement: 585 lbs Water: 0.41</p>	<p>1999 CONSTRUCTION DELIVERY</p> <p>Batch Tickets</p> <p>Cement: 611-680 lbs Water: 0.38</p>	<p>2010 IN-SITU (PSI &amp; CTL)</p> <p>Calculations based on Petrography and chemical test</p> <p>Cement: 612-654 lbs* Water: 0.50 +/-0.05</p>
---	---	--

Measured per cubic yard of concrete.  
\* As calculated per ASTM C1324.





# MATERIALS: WATER : CEMENT RATIO



Photograph #1 - Sample 06033-1. Change in paste color can be seen at top surface and lower right corner.



Photograph #2 - Sample 06033-2. Color change can be seen in paste at top surface as well as the bulk paste.



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT

January 20, 2011


Please see Volume 2 for the complete  
PSI report dated January 14, 2011



MILLER  
CONSULTING  
ENGINEERS, INC.



# MATERIALS: MICROFRACTURES IN THE CONCRETE



Carlson	PSI	CTL Group
<b>MINIMAL</b>	<b>EXCESSIVE</b>	<b>EXCESSIVE</b>
<p>Excessive Microfractures would tend to indicate overstressed concrete and a potential for leading to in place concrete strength degradation. <b>(It gets weaker.)</b></p>		

# MATERIALS: DEBONDING



Fig. 7 Image showing freshly fractured surfaces of Cores 2A-TCP and 5D-BOTTOM. The fracture surfaces pass around almost all coarse aggregate particles indicating a weak paste-aggregate bond. Scale is marked in inches.




Fig. 8 Stereomicroscope image of a cut and lapped cross-sectional surface of Core 3C-MIDDLE, showing coarse aggregate particles exhibiting lighter paste rims (arrows). Scale increments are 0.04 in.



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011

Please see Volume 2 for the complete  
CTL Group report dated December 15, 2010





# MATERIALS: DEBONDING AND MICROFRACTURING




Fig. 9 Stereomicroscope Image of a cut and lapped cross-sectional surface of Core 5D BOTTOM, showing microcracks along the periphery of coarse aggregate particles and in the nearby paste (arrows). Scale increments are 0.04 in.




Fig. 10 Stereomicroscope image of a cut and lapped cross-sectional surface of Core 3C-MIDDLE, showing microcracks in the paste between coarse aggregate particles (arrows). The image was taken using oblique illumination shortly after the surface was wetted to highlight the microcracks. Field of view is approximately 0.5 in. across.



Please see Volume 2 for the complete  
CTL Group report dated December 15, 2010



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011







# MATERIALS: SEALANT



# MATERIALS: CURTAINWALL SELECTION

STANDING WATER IN WINDOW



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011





# CONSTRUCTION ISSUES: INSTALLATION ISSUES



REINFORCING BAR EXPOSED AT THE BOTTOM OF THE BUS MALL SLAB



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011



MILLER CONSULTING ENGINEERS, INC.



# CONSTRUCTION ISSUES: SITE CLEANUP



DEBRIS ON THE FORM WORK CAST INTO THE  
BUS MALL SLAB





# CONSTRUCTION ISSUES: INCORRECT INSTALLATION



DEBRIS IN  
CASTING BED

REINFORCING BARS  
LAYING IN  
CASTING BED

REBAR BENT AND  
NOT REPAIRED  
DURING  
CONSTRUCTION


# PROBLEMATIC CONSTRUCTION: SITE SUPERVISION

Wood Chips Cast Into Concrete Column



SCREWDRIVER WITH  
2 INCHES OF  
EMBEDMENT

# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION ISSUES: BASIC DIAGRAM




Please see Appendix 3 for a fully detailed survey

# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION ISSUES: CONCRETE FLOOR SLAB BEHAVIOR

- Initial low strength concrete leads to more deflections
- Long term creep contributes to the deflections
  - Deflections create stress in the slab
  - This stress manifests into microfractures
  - Microfractures contribute to lower strength concrete




# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION DEFLECTION OBSERVED SLAB DEFLECTION



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011



# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION DEFLECTION OBSERVED SLAB DEFLECTION



Second Floor




MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011





# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION DEFLECTION OBSERVED SLAB DEFLECTION



Third Floor




MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011



MILLER CONSULTING ENGINEERS, INC.



# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION DEFLECTION OBSERVED SLAB DEFLECTION



Fourth Floor




MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011





# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION DEFLECTION OBSERVED SLAB DEFLECTION




MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011



MILLER CONSULTING ENGINEERS, INC.



# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION ISSUES: WALLS



# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION ISSUES: DOORS





# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION ISSUES: CASEWORK





# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION: SHRINKAGE AND SHORTENING

← BRICK RESISTANCE      BRICK RESISTANCE →



SE Corner

SLAB MOVEMENT →



SW Corner


SLAB MOVEMENT →

# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION: BUILDING STRUCTURE

BRICK RESISTANCE →



NE Corner ← SLAB MOVEMENT



BUCKLED STEEL STUD

# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION: BUILDING ENVELOPE


SHEARED SEALANT



OUT OF PLANE  
MOVEMENT




DEBONDED  
MORTAR JOINT





# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION:

## BUILDING ENVELOPE



COMPRESSED SEALANT



SEPARATED FLASHING



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011





# RESULTS OF DESIGN, MATERIALS, AND CONSTRUCTION: COLUMN GAP AT THE BUS MALL SLAB

4 1/2 INCHES  
AT TOP



3" INCHES  
AT BOTTOM




# IMPACTS: OVERALL

- Relocation of all tenants within 60 days
- Closure of the Bus Mall and Parking Garage
- Bus Mall has moved to three different locations
- Unanticipated Costs
- Public Discourse



# IMPACTS: DEPARTMENTAL RELOCATION



# REMEDICATION OPTIONS:

## CONSIDERED

- Fiber reinforced polymer (FRP) to strengthen existing slab
  - Additional structural slab on top
- In-place concrete too weak, dead load balancing too great
  - Must be post-tensioned (thicker than existing) at 12-16 inches, or . . .
  - Conventional slab but substantially thicker at 16-20 inches, and . . .
- Slab can't support itself
  - Drop beams below existing slab or rely on existing slab to perform as intended with tendon testing
- Needs drop panels or slab bands for punching shear
  - Significant column, foundation and shear wall modifications
- Needs to relieve stress in existing slab
- External post-tensioning
  - Significant column, foundation and shear wall modifications
- In-place concrete too weak, dead load balancing too great
  - Drop beams below existing slab or rely on existing slab to perform as intended with tendon testing
- Slab can't support itself
  - Significant column, foundation and shear wall modifications
- Needs drop panels or slab bands for punching shear
  - Significant column, foundation and shear wall modifications
- Needs to relieve stress in existing slab



# REMEDIATION OPTIONS:

## CONSIDERED

- Fiber reinforced polymer (FRP) to strengthen existing slab
  - Additional structural slab on top
  - Must be post-tensioned (thicker than existing, 24-36 inches, or . . .
  - Conventional slab but substantially thicker at 16-20 inches, and . . .
- In-place concrete too weak, dead load balancing too great
  - Drop beams below existing slab or rely on existing slab to perform as intended with tendon testing
- Slab can't support itself
  - Significant column, foundation and shear wall modifications
- Needs drop panels or slab bands for punching shear
- Needs to relieve stress in existing slab
- External post-tensioning
  - Drop beams below existing slab or rely on existing slab to perform as intended with tendon testing
- In-place concrete too weak, dead load balancing too great
  - Significant column, foundation and shear wall modifications
- Slab can't support itself
- Needs drop panels or slab bands for punching shear
- Needs to relieve stress in existing slab

# REMEDICATION OPTIONS: PROPOSED

## BUILDING

- Create additional structural system
  - Steel beams to divide column bays
- Augment existing structure
  - Increase size of columns
  - Increase size of foundations
  - Install FRP on top of floor slabs in limited locations
  - Increase thickness of shear walls

# REMEDIATION OPTIONS: PROPOSED


- Mechanical system changed from air-based to water based radiant system
  - Demolish existing air handlers, ducts and terminal units
  - Cooling tower on roof
  - Chillers and pump room in basement
  - Boiler room in basement
  - Radiant panels as new ceiling
  - Uses significantly less energy than current air-based system
  - Unified system: Not ad-hoc or mismatched

# REMEDIAATION OPTIONS: PROPOSED

- Other building systems will need significant modification
  - Electrical distribution from the main risers
  - Telecommunications from the closets
  - Lighting system
  - Fire sprinklers from the main riser
  - Ceilings, grids and registers




# REMEDIATION OPTIONS: PROPOSED



Columns increase in size


New structural  
steel beams

# REMEDIATION OPTIONS: PROPOSED





# REMEDIATION OPTIONS: PROPOSED (AUGMENTED)



Columns increase in size

New structural  
steel beams

# REMEDIATION OPTIONS: PROPOSED (AUGMENTED)



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011




MILLER  
CONSULTING  
ENGINEERS, INC.





# REMEDICATION OPTIONS: PROPOSED



- Radiant Panel (water)
- Existing ceiling height maintained
- Air-based system can't fit into space

# REMEDIATION OPTIONS: CONSIDERED

## BUS MALL

- Create additional structural system
- Steel beams to divide column bays
- Augment existing structure
- Increase size of columns
- Increase size of foundations
- Install FRP on top of floor slabs in limited locations
- Increase thickness of shear walls
- Locations for different car sizes heavily controlled

## PROPOSED


- Demolish existing and rebuild new

# REMEDIATION OPTIONS:

## CONSIDERED

COLUMNS INCREASE IN SIZE

NEW STRUCTURAL  
STEEL BEAMS



# REMEDIATION OPTIONS: CONSIDERED

10



- Max 7'-0" clearance unless additional excavation is undertaken

MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011



MILLER  
CONSULTING  
ENGINEERS, INC.






# REMEDICATION OPTIONS: PROPOSED

## NORTH BLOCK

- Existing damage is extensive
- Additional testing could be done
- Value of asset compared to extent of repairs is less
- Demolish

# REMEDICATION OPTIONS: SUMMARY



### CONSTRUCTION COSTS

\$1,588,475	\$28,800,027	\$33,623,272	\$291,423	\$7,827,685	\$7,127,773	\$122,462	\$2,879,460	\$2,432,198
-------------	--------------	--------------	-----------	-------------	-------------	-----------	-------------	-------------

### TOTAL PROJECT COSTS

\$2,011,535	\$39,696,585	\$46,336,530	\$368,509	\$10,375,284	\$9,660,695	\$147,926	\$3,421,730	\$3,141,935
-------------	--------------	--------------	-----------	--------------	-------------	-----------	-------------	-------------

Demolition    Remediation    Replace    Demolition    Remediation    Replace    Demolition    Remediation    Replace

**Courthouse Square**

**Bus Mall**


**North Block**



# NEXT STEPS

WE ARE HERE

SOLUTIONS TASK FORCE




MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011



# NEXT STEPS

## WE ARE HERE SOLUTIONS TASK FORCE



PARKING GARAGE/BUS MALL STRUCTURE REMEDIATION








# QUESTIONS

## APPENDICES

- Building Overview
- Testing Locations
- Punching Shear Locations
- Column Loading
- Slab Reinforcing Deficiencies
- Shear Wall Deficiencies



# BUILDING OVERVIEW



Garage Levels



**Cherriots**  
SINCE 1933


MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011



**SERA**



# BUILDING OVERVIEW




Ground Floor



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011



# BUILDING OVERVIEW



## Second Floor

- WINDOW SILL CRACK
- GYP WALL CRACK
- CMU/CONC WALL CRACK
- ▼ CASEWORK/FURN ISSUE
- DOOR FUNCTION ISSUE
- ⊗ CEILING GRID BUCKLE IN FIELD
- ⊗ CEILING SOFFIT ISSUE
- WINDOW SILL CRACK
- GYP WALL CRACK
- CMU/CONC WALL CRACK
- CASEWORK/FURN ISSUE
- CEILING WALL ANGLE BUCKLING
- FLOOR/SLAB CRACK
- WINDOW, CRACK OR DETERIORATION/ DEFORMATION AT EXTERIOR WALL
- WINDOW; BROKEN/DEFECTIVE IGU
- WINDOW; STAINING & EVIDENCE OF WATER AT WINDOW/SILL
- WINDOW; STAINING & EVIDENCE OF WATER AT WALL OR CLG
- WINDOW; INTERIOR GASKET SHORT/INCOMPLETE




**Cherriots**  
SALES & SERVICE





# BUILDING OVERVIEW




*Cherriots*  
SALES & SERVICE



MILLER CONSULTING ENGINEERS, INC.



# BUILDING OVERVIEW



Fourth Floor




**Cherriots**  
SALES • SERVICE • SUPPORT





# BUILDING OVERVIEW



Fifth Floor



*Cherriots*  
SALVAGE REUSE REBUILD

MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011



MILLER CONSULTING ENGINEERS, INC.



# BUILDING OVERVIEW



## Legend


- no with press. diff. ✓
- sealant failed, compressed, or split
- failed IGU
- short gasket
- crack
- open frame joint or frame issue
- control joint issue
- Test P / F
- P = pass
- F = fail

South Elevation






# BUILDING OVERVIEW




North Elevation



# BUILDING OVERVIEW



West Elevation




East Elevation



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011



# TESTING LOCATIONS – BUS MALL SITE



C	P
CARLSON	
PSI	
CTL	

C	P
CARLSON	
PSI	
CTL	



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011

COURT STREET




MILLER CONSULTING ENGINEERS, INC.





# TESTING LOCATIONS – GROUND FLOOR



 Pour Strips



MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011




MILLER CONSULTING ENGINEERS, INC.






# TESTING LOCATIONS – SECOND FLOOR




# TESTING LOCATIONS – THIRD FLOOR




 Pour Strips



# TESTING LOCATIONS – FOURTH FLOOR



# TESTING LOCATIONS – FIFTH FLOOR




 Pour Strips






# BUILDING FOOTING DEFICIENCIES



 Punching Shear Stress More Than 33% Greater Than Code Allowance

 Punching Shear Stress More Than 10% Greater Than Code Allowance


# FIRST FLOOR: PUNCHING SHEAR STRESS PLAN



- Exceeds Code Stress Limits w/5,000 psi Concrete and Actual Core Strengths
- Exceeds Stress Limits using Actual Code Strengths
- Stress More than 33% Greater than Code Allowable Based on Actual Core Strengths
- Stress more than 33% Greater than Code Allowance Based on Original Design Strength (5,000 psi) and Actual Core Strengths



# SECOND FLOOR: PUNCHING SHEAR STRESS PLAN



Exceeds Code Stress Limits w/5,000 psi Concrete Design Strength

Exceeds Stress Limits using Actual Code Strengths


Stress More than 33% Greater than Code Allowable Based on Actual Core Strengths ("Dangerous" Condition)

Stress more than 33% Greater than Code Allowance Based on Original Design Strength (5,000 psi) and Actual Core Strengths ("Dangerous" Condition)



# THIRD FLOOR: PUNCHING SHEAR

## STRESS PLAN



Exceeds Code Stress Limits w/5,000 psi Concrete Design Strength

Exceeds Stress Limits using Actual Code Strengths


Stress More than 33% Greater than Code Allowable Based on Actual Core Strengths (“Dangerous” Condition)

Stress more than 33% Greater than Code Allowance Based on Original Design Strength (5,000 psi) and Actual Core Strengths (“Dangerous” Condition)





# FOURTH FLOOR: PUNCHING SHEAR STRESS PLAN



Exceeds Code Stress Limits w/5,000 psi Concrete Design Strength


Exceeds Stress Limits using Actual Code Strengths

Stress More than 33% Greater than Code Allowable Based on Actual Core Strengths ("Dangerous" Condition)

Stress more than 33% Greater than Code Allowance Based on Original Design Strength (5,000 psi) and Actual Core Strengths ("Dangerous" Condition)



# FIFTH FLOOR: PUNCHING SHEAR STRESS PLAN




█ Exceeds Code Stress Limits w/5,000 psi Concrete Design Strength  
█ Exceeds Stress Limits using Actual Code Strengths  
█ Stress More than 33% Greater than Code Allowable Based on Actual Core Strengths ("Dangerous" Condition)  
█ Stress more than 33% Greater than Code Allowance Based on Original Design Strength (5,000 psi) and Actual Core Strengths ("Dangerous" Condition)

█ Exceeds Code Stress Limits w/5,000 psi Concrete Design Strength  
█ Exceeds Stress Limits using Actual Code Strengths  
█ Stress More than 33% Greater than Code Allowable Based on Actual Core Strengths ("Dangerous" Condition)




# BUS MALL: PUNCHING SHEAR STRESS PLAN



Stress more than 33% Greater Than Code Allowance



# BUS MALL: PUNCHING SHEAR STRESS PLAN



Column Exceeds Code Limits  
Under Dead Load Only




MARION COUNTY COURTHOUSE SQUARE STRUCTURAL REMEDIATION PROJECT January 20, 2011






# ROOF COLUMNS





All Columns within 10% of Design Capacity

-  More than 10% Beyond Code Limit
-  More than 33% Beyond Code Limit




# FIFTH FLOOR COLUMNS





-  More than 10% Beyond Code Limit
-  More than 33% Beyond Code Limit



# FOURTH FLOOR COLUMNS




 More than 10% Beyond Code Limit

 More than 33% Beyond Code Limit




# THIRD FLOOR COLUMNS



- More than 10% Beyond Code Limit
- More than 33% Beyond Code Limit




# SECOND FLOOR COLUMNS



- More than 10% Beyond Code Limit
- More than 33% Beyond Code Limit




# FIRST FLOOR COLUMNS




■ More than 10% Beyond Code Limit  
■ More than 33% Beyond Code Limit



# TYPICAL SLAB TOP REINFORCING STEEL DEFICIENCIES AT FIRST FLOOR



# TYPICAL SLAB TOP REINFORCING STEEL DEFICIENCIES AT 2ND-5TH FLOORS + ROOF




**Keynotes**


1. Insufficient Top Reinforcing under Service Loads
2. Insufficient Top Reinforcing for Flexural Strength
3. Insufficient Top Reinforcing for Service and Strength
4. Column strip top Stress Exceeded
5. Insufficient Top Reinforcing Steel at 3<sup>rd</sup>, 4<sup>th</sup> Floors




# TYPICAL SLAB BOTTOM REINFORCING STEEL DEFICIENCIES AT FLOORS 2 - ROOF




# TYPICAL SLAB TOP REINFORCING STEEL AT BUS MALL



# TYPICAL SLAB BOTTOM REINFORCING STEEL AT BUS MALL




# FIRST FLOOR SHEAR WALL DEFICIENCIES




- Shear Strength Deficiency
- Boundary Element Deficiency
- Header Beam Deficiency



# SECOND FLOOR SHEAR WALL DEFICIENCIES




# THIRD FLOOR SHEAR WALL DEFICIENCIES




- Shear Strength Deficiency
- Boundary Element Deficiency
- Header Beam Deficiency

# FOURTH FLOOR SHEAR WALL DEFICIENCIES



-  Shear Strength Deficiency
-  Boundary Element Deficiency


# FIFTH FLOOR SHEAR WALL DEFICIENCIES



- Shear Strength Deficiency
- Boundary Element Deficiency



# ROOF SHEAR WALL DEFICIENCIES



Shear Strength Deficiency

Boundary Element Deficiency





